



ADDENDUM NO. 2

Project No: PTC 2020-02
October 1, 2020

Project: FIRE ALARM SYSTEMS & MISC. UPGRADES
VARIOUS SITES
SAULT STE. MARIE, ONTARIO

The following additions, deletions, and amendments are hereby made a part of the drawings and specifications of the above project.

1) 53 Chapple Ave Apartment Building: - Reference Drawings E1.1 to E1.4

The heat detector shown in each Apartment Suite is supposed to be labelled as “New Heat Detector”, and it will require new wiring installed within new painted EMT conduit. The drawings erroneously have them labelled as “Rp”, indicating that they are existing and that they only need to be replaced. Revise drawings and scope of work accordingly.

2) 55 Chapple Ave Apartment Building: - Reference Drawings E2.1 to E2.9

The heat detector shown in each Apartment Suite is supposed to be labelled as “New Heat Detector”, and it will require new wiring installed within new painted EMT conduit. The drawings erroneously have them labelled as “Rp”, indicating that they are existing and that they only need to be replaced. Revise drawings and scope of work accordingly.

Liza Chikoski, A.Sc.T.

Infrastructure & Asset Manager

Housing | Social Services

P.O. Box 277 | 180 Brock Street
Sault Ste. Marie, Ontario, P6A 5L8
CA

Phone: 705-759-5131

Fax: 705-759-5212

Cell:

Email: L.Chikoski@socialservices-ssmd.ca

Web: <http://www.socialservices-ssmd.ca>



Social Services | Services Sociaux
Zhawenimi-Anokiitaagewin

Sault Ste. Marie District

Here to help.
Ici Pour Aider.



Ontario Works
Ontario au travail



Housing Services
Services de Logement



Early Years
Services
Services pour le
petit enfant



Paramedic
Services
Paramédicaux

Housing Services
180 Brock Street
Sault Ste. Marie, ON
P6A 3B7

Tel: 705-946-2077
Fax: 705-946-5628
www.socialservices-ssmd.ca